## **Consulting Engineer**

Registered Professional Engineer of Queensland

General Manager Ballina Shire Council PO Box 450 BALLINA NSW 2478 27 April 2018 Ref No. 914108

Dear Sir,

#### Further Assessment of Damage to Property at 7 Castle Drive, Lennox Head

This is to advise that inspections of 7 Castle Drive, Lennox Head were conducted by the undersigned on 23 February and 27 April 2018. The purpose of the inspections was to investigate and report on any changes to the tree root damage to the dwelling and associated concrete pavements and masonry walls that has occurred since April 2017.

This report should be read in conjunction with the previous report dated 20 April 2017.

#### 1. Site Observations

The observations are described in the Photographs No. 1 to 12 attached and are summarised in the table below.

Building Element	Observed Change Since 6 April 2017		
Leaning pillar at the dwelling entry door	None evident		
Driveway slab	Slab has lifted a further 10mm at the garage entry		
Masonry screen fence next to the garage	This wall has lifted by an additional 10mm and rotated		
	a further 4mm away from the dwelling		
Path on the western side of the house	None evident		
Diagonal crack in the brick wall at the	None evident		
south-eastern corner of the house			

#### 2. Conclusions

It can be concluded that between 6 April 2017 and 27 April 2018 the extent of damage to the driveway and masonry screen fence at the front of the dwelling at 7 Castle Drive has increased. This has most likely resulted from the continued growth of the root system of the adjoining fig tree. However no other significant increase in movement within the structure of the dwelling was observed.

Yours faithfully,



Craig Zerk Consulting Engineer

Encl.:

1. Photos. No. 1 to 12

ACN: 115 021 979			ABN: 41 115 021 979
PO Box 159 BALLINA NSW 2478		Bank Details: BSB 062 502 Account: 10412435	
2 Elizabeth Street EAST BALLINA NSW 2478	Tel: 02 6686 4992	Mobile: 0419 237 984	Email:cmzeng@bigpond.com



Registered Professional Engineer of Queensland



Photo No. 1 - Leaning brick pillar at the entry to the house as photographed on 6 April 2017.




Photo No. 2 – The leaning in the brick pillar at the entry as photographed on 27 April 2018. The lean does not appear to have deteriorated over the past 12 months.

 ACN: 115 021 979
 ABN: 41 115 021 979

 PO Box 159 BALLINA NSW 2478
 Bank Details: BSB 062 502 Account: 10412435

 2 Elizabeth Street EAST BALLINA NSW 2478
 Tel: 02 6686 4992
 Mobile: 0419 237 984
 Email:cmzeng@bigpond.com

## **Consulting Engineer**

Registered Professional Engineer of Queensland




Photo No. 3 – Lifted concrete driveway slab abutting the garage floor slab as photographed on 6 April 2017. At the time the step at the joint was measured at 25mm high.



Photo No. 4 – Lifted concrete driveway slab abutting the garage floor slab as photographed on 27 April 2018 when the step at the joint was measured at 35mm high.

 ACN:
 115 021 979
 ABN: 41 115 021 979

 PO Box 159 BALLINA NSW 2478
 Bank Details: BSB 062 502 Account: 10412435

 2 Elizabeth Street EAST BALLINA NSW 2478
 Tel: 02 6686 4992
 Mobile: 0419 237 984
 Email:cmzeng@bigpond.com



## **Consulting Engineer**

Registered Professional Engineer of Queensland



Photo No. 5 – A step in a contraction joint in the driveway slab at the property boundary as photographed on 6 April 2017.



Photo No. 6 – The step in the contraction joint in the driveway slab at the property boundary as photographed on 27 April 2018 did not exhibit any significant change over the past 12 months.

 ACN: 115 021 979
 ABN: 41 115 021 979

 PO Box 159 BALLINA NSW 2478
 Bank Details: BSB 062 502 Account: 10412435

 2 Elizabeth Street EAST BALLINA NSW 2478
 Tel: 02 6686 4992
 Mobile: 0419 237 984
 Email:cmzeng@bigpond.com



Registered Professional Engineer of Queensland



Photo No. 7 – As photographed on 6 April 2017, lifting and rotation of the brick privacy wall on the western side of the garage had opened up a gap in the vertical joint with the house.



Photo No. 8 –The vertical joint between the brick privacy screen and the house as photographed on 27 April 2017. This joint has widened by about 4mm and the privacy screen has lifted by about 10mm over the past 12 months.

 ACN:
 115
 021
 979
 ABN:
 41
 115
 021
 979

 PO
 Box
 159
 BALLINA
 NSW
 2478
 Bank
 Details:
 BSB
 062
 502
 Account:
 10412435

 2
 Elizabeth
 Street
 EAST
 BALLINA
 NSW
 2478
 Tel:
 02
 6686
 4992
 Mobile:
 0419
 237
 984
 Email:cmzeng@bigpond.com

## **Consulting Engineer**

Registered Professional Engineer of Queensland



Photo No. 9 – Separation of the 1.3metre wide path from the wall on the western side of the house as photographed on 6 April 2017



Photo No. 10 – Separation of the 1.3metre wide path from the wall on the western side of the house as photographed on 27 April 2018. The does not appear to have been any significant change since April 2017.

ACN: 115 021 979

PO Box 159 BALLINA NSW 2478

2 Elizabeth Street EAST BALLINA NSW 2478

Tel: 02 6686 4992 N

Bank Details: BSB 062 502 Account: 10412435

ABN: 41 115 021 979

Mobile: 0419 237 984 Email:cmzeng@bigpond.com



Registered Professional Engineer of Queensland



Photo No. 11 – Cracking in the brick wall at the south-eastern corner of the house as photographed on 6 April 2017.

 ACN:
 115
 021
 979
 ABN:
 41
 115
 021
 979

 PO
 Box
 159
 BALLINA NSW 2478
 Bank
 Details:
 BSB
 062
 502
 Account:
 10412435

 2
 Elizabeth
 Street
 EAST
 BALLINA NSW 2478
 Tel:
 02
 6686
 4992
 Mobile:
 0419
 237
 984
 Email:cmzeng@bigpond.com

# Craig Zerk Consulting Engineer

Registered Professional Engineer of Queensland



Photo No. 12 – Cracking in the brick wall at the south-eastern corner of the house as photographed on 27 April 2018. This crack does not appear to have deteriorated over the past 12 months.

ACN: 115 021 979

PO Box 159 BALLINA NSW 2478

2 Elizabeth Street EAST BALLINA NSW 2478

Tel: 02 6686 4992

Bank Details: BSB 062 502 Account: 10412435

ABN: 41 115 021 979

Mobile: 0419 237 984 Email:cmzeng@bigpond.com