11.1 Local Traffic Committee Report - August 2014.DOC



11.1 Local Traffic Committee Report - August 2014.DOC



Ross Lane Road Safety Review - Recommended Actions			
Item	Short Term	Medium Term	Long Term
1	Relocate the existing RCL65 advisory warning sign and install new CL65	Develop a program of works for the ongoing upgrading of road infrastructure such as shoulders	Undertake road works to improve the alignment, pavement, capacity and width of Ross Lane.
2	Install new advisory warning sign for eastbound RCL at the highway	Widen shoulders to provide a minimum 1.0 m of seal.	Widen culverts.
3	Review speed limit for western hilly section of Ross Lane	Develop a strategic plan that identifies the required improvements and new infrastructure required for traffic growth	Realign western section to improve safety.
4	Regularly monitor accident data to identify any trends	Provide improved turning facilities at existing road junctions.	
5	Review sight lines at existing junctions and roundabout at the highway	Consider any future bus, pedestrian and bicycle infrastructure needs for inclusion in future programs	
6	Review existing bus bays and seek funding for improvements	Carry out road works to improve bus bays.	
7	Review SCRIM for existing curves	Develop a program of works for the ongoing upgrading of substandard road curves.	Upgrade substandard road curves